

SICILLI TİCARET NO. 27018

TESİS TARİHİ: 1912

İTHALATÇI GRUP V. NO. 1913

İHRACAT RUHS. NO. 2401

Necati Pehlivan

ARMATÖR

VAPURCULUK - KÖMÜRCÜLÜK - NAKLIYAT - TİCARET
İTHALAT - İHRACAT - MÜMESSİLLİK - KOMİSYON - TAHHÜT

WRECK
SECTION

TELEFONLAR No. 617

MERKEZ : 40815
KÖMÜR DEPOSU: 36-195
EV : 84568

TELGRAF ADRESİ :
PEHLIVAN - İSTANBUL

WRECK
SECTION

No. 617

RECEIVED

30 OCT 1954

ack

1. 11. 54

İSTANBUL, 27/10/1954

Merkez: Arzu han, Rıhtım cad. No. 247 - Galata
Kömür Deposu: Tramvay cad. No. 35 - Kuruçeşme

Your Ref.
Publications II3/54

Dear Sir,

I am in receipt of your letter of the 14th instant and confirm that the motorship 'NECATİ PEHLİVAN' II "stranded and sank west of Lagskar on the 26th September, 1954.


There is no objection to a casualty record being inserted against the ship's name in the Society's Register Book, and to the ship's class being expunged.

M.M.C.C.

2,192.

Yours faithfully,

Necati Pehlivan




The Secretary,
Lloyd's Register of Shipping
71, Fenchurch Street,
London, E.C.3.

4386

© 2020

007184-007193-0198



Lloyd's Register
Foundation

PUBLICATIONS

R. a. f.

Miss Holley



© 2020

Lloyd's Register
Foundation