

Built at *Ayr*
When built *1906* Launched *2*
By whom built *Alba S. B.*
Owners *Spillers & Bakers*

Received from Chief Surveyors

Report *EE*. No. *24017*

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

First entry

~~When due~~

1 Dr (Stt) Will Deck

W.B. = Cell DB f 74' 825 FPT 195 APT 45

BK 7" 3BH pt. Gen. Ploegh A9 CP Q 84' B10' F22' Nohy Aft.

C. A. J.
22/5/06

LARS

002184002193 = 0218

© 2020

Lloyd's Register

thickness $P. \text{ Pine } 2\frac{5}{8} + 2\frac{3}{4} = 5\frac{1}{2}$

BULKHEADS.

Number.

STIFFENERS.

Sing

Don
Fra

1	2
3	4