

COPY

29th November, 1946.

Dear Sir,

S. With reference to Glasgow First Entry Report No.71171 on the Motorship "NERITOPSIS", I have to inform you it is concluded the thickness of the upper deck plating at the engine casing sides is .62", as approved, and not .42", as reported, but I shall be glad if you will be good enough to confirm that this is so.

Yours faithfully,

Clerk to the
Classification Committee.

The Secretary,
GLASGOW.



© 2020

Lloyd's Register
Foundation

002194-002205-0025