



Lloyd's Register of Shipping.

Royal Bank Buildings,
28, Constitution Street,
Leith, 8th March, 1933.



Reference

8

Dear Sir,

In reply to the Classing letter dated 3rd instant with reference to the s.s. "LONDON QUEEN", we beg to inform you that the bridge side is formed of a single plate with treble riveted butt lap to shell plating aft of same.

The spare gear required by the Rules has been put on board the vessel, and we regret that this was not definitely stated on our report No. 18353.

We are, Dear Sir,

Yours faithfully,

THE SURVEYORS.

Per.

John Houston

The secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

002194-002205-0171

Referred to the Chief Ship Surveyor,

hms

9 MAR 1933

also for Mr. Spinks to note.

[Handwritten signature]

[Handwritten mark]

[Faint handwritten text, possibly "John Jones"]

1st

THE SURVEYOR

ALLIANCE

THE TANK, etc

RECEIVED FOR THE TANK AND THE TANK

WATSON

WATSON



© 2020

Lloyd's Register
Foundation