

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name _____

Official No. _____

Port of Registry _____

This ship has been under survey at _____

on _____

195 _____

and the following alterations to the conditions of

assignment of loadlines have now been effected/found:—

Alterations to from Report 8 2161 AmsterdamAmidshipsC Deck Saloon Ft 61-67 removed, and after bulkhead removed, hatch coaming lengthened to 370 in. see Drawing.D Deck Accth removed, ft 47-60, and new W.T. Bulkhead erected at Ft 60. casing round hatch removed and new coaming (new flush) made.Poep. Poep deck removed from Ft 11-18 and 2 new hatchways made.E Deck Deck house removed ft 10-18. Accth removed in rear of Poep and 2 hatchways made.

A copy of this Report has been placed on board.



© 2021

Lloyd's Register
Foundation

002222-002228-0171