

4 MAY 1956

Led 4681

Index No. _____
(For London Office use)

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "DONA FLORA" Official No. 147772Port of Registry HULL.This ship has been under survey at Goole. (See Hull Fbd. Rpt. C11(a) No.).

on the 4th April, and subsequently, 195 6 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~:—

An additional access hatch to No.1 Hold has been fitted by Owners, starboard side of freeboard deck abreast main mast.

Access is by means of an opening in deck plating between adjacent beams, approx. 30" x 20" with well rounded corners.

An efficient fabricated $\frac{3}{8}$ " steel coaming 38" in height with E.W. attachment to deck. Coaming is also extended below deck and E.W. as compensation.

The hatch is closed by an efficient hinged steel W.T. cover secured by turnbuckles.

McWiggin
SURVEYOR TO LLOYD'S REGISTER
OF SHIPPING, H U L L.
APRIL, 1956.

9.5.56

A copy of this Report has been placed on board.



© 2020

Lloyd's Register
Foundation

002241-002248-0150