

Are the Bilge Suctions in the Machinery Space led from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to

Are all connections with the sea direct on the skin of the ship Yes.

Are they Valves or Cocks both.

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates Yes.

Are the Discharge Pipes above or below the de

Yes. Are the Blow Off Cocks fitted with a spigot and brass

002279-002288-0027

Spar Dredger No 75.

Grk. 18437.


submitted the Greenock Surveyor he requested & read the approved plan of the Boilers

[Signature]

6/8/55.

SPARE GEAR. State the articles supplied.

2 main bearing bolts & nuts. 2 top end bolts & nuts. 2 bottom end bolts & nuts. 1 set of feed valves & seats for main & auxiliary feed pumps. 1 set of air pump valves. 2 eccentric bolts & nuts. 4 feed check valves. 24 condenser tubes. 2 bilge pump valves 50 f
1 set of springs for safety valves. 12 boiler tubes. Assorted bolts and



© 2020

Lloyd's Register
Foundation

tight steel
into the cargo or ma
worked
Working Press
arded? ✓
Don