

Th

"PASS OF BRANDER"

In reply to telephonic enquiry Mr. Wilson states ✓
the new bilge pump has now been delivered and will be fitted
at the first convenient opportunity, but that he is unable
to say when this is likely to arise.

He is aware of the fact that the LMC notation is
not being assigned until this pump is fitted.

W.C.

2.1.48.



© 2021

Lloyd's Register
Foundation

002298-002304-0167
002298-002304-0167