

Less above  
 Engine  
 TONNAGE  
 Less Engi  
 Less Navig  
 Register  
 as cut o

"Ribensborg"

F.E.

Received by Chief Ship Surveyor 25. 5. 01

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Steel S.S. "Segontian" Report Mdb No. 3098

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . . .	✓	✓
Spar Sheerstrake . . .	✓	✓
Description of Framing:— <i>Deep (bulb angle) framing.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\ddagger$  100 A1 ("Steel") as recommended.

$\ddagger$  100 A1 ("Steel")  
 1 Dh (pt Lrm & pt SH) & deep framing.  
 W.B = D Ba & u E 79' u B 15' f 92' 352t APT 24t  
 FK 4 BH Cem A & CP.  
 Q 82' B 56' RFD 85' 721'

J.H.T.  
 25/5/01

C.A.P.

WEB  
 BRAC