

113 MAR 1945

Rpt. C. 11 (Contd.)

Index No. _____

Lloyd's Register of Shipping.

Vol. 375

Ship's Name S.S. "ROTHER"

Official No. 128883

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines
in _____

Steel hinged doors fitted with turnbuckles, have now been fitted on Bridge Front in place of storm boards in riveted channels.

The Load Line Certificate has been altered accordingly, and stamped, in the space re closing Appliances.

J.M. Bell

Leith, 28. 2. 45

*Noted
14 MAR 1945
H.P.*

