

10 JUL 1951

29584

Lloyd's Register of Shipping.

Ship's Name "S A M A R I A"

Official No. 145923.

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in

ALTERATIONS:

The following single stairway openings were made in the Vessel at this time:-

Upper Promenade Deck (Frs. 97-100 (S))

Opening 8'-9" x 3'-8" with efficient compensation of doublers on deck and fore and after below.

Promenade Deck Frs. 97-100 (S)

Opening 8'-9" x 3'-8" with efficient compensation of Doublers on deck and fore and after below.

Main Deck. Frs. 97-100 (S)

Opening 8'-9" x 3'-8" with efficient compensation of Doublers on Deck and fore and after below.

Main Deck. Frs. 79-82 (S).

Opening 8'-9" x 3'-5" with efficient compensation of Doublers on deck and fore and after below.

Main Deck Frs. 59-61 (P)

Opening 8'-9" x 3'-2" with efficient compensation of Doublers on deck and fore and after below.

The above stairway openings are enclosed within houses having doors of efficient construction and capable of being closed from both sides and having sills of adequate height

Hatch Trunkways: The following trunkways extended at this time and the trunkways to have a carrying capacity of no more than 100 cu.ft. per ton to Freeboard Deck level -

No.2 Hatch extended from 'A' to 'B' Deck.

No.3 " " " 'A' to 'B' Deck.

No.4 " " " 'R' to 'B' Deck.

No.7 " " " 'R' to 'B' Deck. ✓

Additional Storm Valves.

7 W.C. Discharges 5 @ 4" dia. and 2 @ 3" diam. from 'R' Deck. *Discharges fitted with stem valves secured at all times and 4" dia. stem valves secured to First Dk.*

4 Deep Tank overflow discharges 4 @ 6" diam. *above 16" dia. B" Dk. approved by N.O.T.*

2 Sewage Tank discharges @ 4" diam. *Discharges fitted with secured stem valves and an ordinary stem valve.*

The insulation in No.3 Lower Tween Deck deleted at this time.

The insulation in Chambers at No.1 and No.6 Holds renewed at this time.

Jas. B. Struthers
Lloyd's Register of Shipping
Glasgow 2/6/51
© 1920
Lloyd's Register
Foundation