

Cherbourgais No 6

Im.821.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S.S. "ABEILLE N° 19"*

Rpt. *Hull*

No. *35778*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *34.25*

Depth "d" *10.96*

Framing: Table No. *3*

Description *Angle frames as approved*

Longitudinal No. *2740*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{6.53}{1}$

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, *See endorsement dated 22.1.25* and it is submitted she is eligible to be classed ~~100A~~ ¹ *for towing purposes.*

+ 100 A.1. (steel) *for towing purposes.*

1 9/16" (stl).

F.P.T. 6t. A.P.T. 15t.

B.K. 6 1/2" Cem. Lloyds A.F.C.P.

See letter

The surveyors should be requested to state whether the butts of the yardboard strake are overlapped or strapped.



© 2020

Lloyds Register Foundation

002352-002361-0180