

M. 273

Ship's name

"AKERA

Survey port

SNG

No. 14975.

Last survey date 18.8.61.

Class is subject to :

(1) Port Main Boiler not being used until repaired and surveyed.

19 SEP. 1961

(2) Both Dynamo Engine Governors being re-examined and tested on vessel's arrival at Reggio Calabria, Italy, where vessel now proceeds direct.

Nature of present survey

VESSEL ON VOYAGE VIA ROTTERDAM TO JAPAN AS AN UNCLASSED VESSEL.

Nature of repairs

Examined After Dynamo Engine following damage alleged to have been sustained when the Aft Dynamo Governor failed to operate. As no spares available on board and the Dynamo beyond temporary repair, the Master elected to proceed with only one Dynamo, and oil lamps for emergency were obtained additional to the navigation lamps together with ample lamp oil for emergency use.

~~XXXXXXXXXXXX~~


IT IS SUBMITTED that this vessel is eligible to remain as ~~class~~ <sup>about</sup> subject as above, and to the After Dynamo not being used until repaired.

To complete surveys partly held

Sailed Moji 9.9  
for Hiroo -  
Sola to Japanese  
breakers  
- Per Lloyd's Index  
19.9.61

18.9.61.

1800-12200-793200



© 2020

Lloyd's Register Foundation