

s/s Northland.

Nur 80372

burg
provided
to be made

It is submitted the Newcastle Surveyors should be informed it is concluded that, pars 7 & 8. Section 41. page 69 of the Rules have been complied with, but they should state if this is so.

Le 18/5/26

yes. See
— Nure ltr 19/5/2005

18/5/20
© 2020
Lloyd's Foundation
002374-002384-0111

ow are stays secured. Double Ruts ✓

the plates: Material { front *Steel* ✓
back *Steel* ✓

Tensile strength { 26/30 tons
26/30 tons

Working pressure by Rules

Thickness