

Lloyd's Register of Shipping.

Ship's Name "NUEVO DOMINICANO" Official No.

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in

The following ventilators have now been removed and the openings efficiently blanked off by means of steel bolted plates on the shelter deck, on the port and starboard sides:-

Port Side of Shelter Deck:

- 36 ventilator openings 4 1/4" x 7" blanked off
- 1 ventilator opening 4 1/2" x 20" " "
- 1 ventilator opening 4 1/2" x 15" " "

Starboard Side of Shelter Deck:

- 31 ventilator openings 4 1/2" x 7" blanked off
- 4 " " 4 1/2" x 20" " "
- 1 " opening 4 1/2" x 15" " "

Y. Jindley

Surveyor to Lloyd's Register of Shipping

August 23, 1949

Maked
SEP 1949

DA



© 2020

Lloyd's Register Foundation