

Lloyd's Register of Shipping.

Ship's Name EMMA BAKKEOfficial No. 7554

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines
in JUNE, 1932.


The overboard scuppers from the 2nd deck have been removed.

Holes in shell plating and in deck stringer plates permanently closed and a 5" screw down scupper valve, operated from upper deck has been fitted on each side in the tonnage well.

Freeing ports in tonnage well also closed for good.

There are two drain pipes each side from the shelter tween deck space to engine room bilges.

(Mmo.Rpt.8 No.1614
dated Oct.,,1937).



© 2020

Lloyd's Register
Foundation

002285-002400-0247