

Received from Chief Engineer Surveyor
EL'S NAME J. H. Senior Rpt. Remen No. 1341

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engines 2 S.E.S.A.

If Boilers fitted with forced draught ✓
Tail Shaft. If fitted with a continuous liner Yes
If fitted with an outside gland of No
approved type

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed Full 3.31

2 Water tube D.D. 200th
2 D.D. 100th.

It is concluded that steam from the water tube Boilers cannot enter the vertical Boilers but this should be confirmed.

J. H. Senior 1/4/31

002401-002409-0053

