

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.

WRECK
SECTION
Telegrams: Committee, London, Telex
Telex No.: 24305

WRECK
SECTION
Telephone: ROYal 91

No.
20th September, 1960.

Dear Sirs,

Classn.(S)

Steamer "ADVISER"

DHCK/SJL

Information has now been received from the Owners that this ship is being towed to Belgium for scrapping.

In the circumstances, this case has now received the consideration of the Committee who have given instructions for a notation "To be broken up" to be entered against the ship's name in the Register Book.


Yours faithfully,

WRECK
SECTION

No. ~~133~~

Deputy Clerk to the
Classification Committee.

The Surveyors,
ANTWERP.



© 2020
002410-002417-0005

Lloyd's Register
Foundation