

With reference to Mr. French's Report No. 14464  
on the new steamer "AFRICA", I am directed to point out that  
the statement given by him shew a discrepancy of some 3½"

No. 2925 AVENUE.

## MEMORANDUM.

NIO J. ARBIB & CO.,  
GRACECHURCH STREET,

LONDON, E.C.

9th Street, New York.

ARBIB, LONDON."  
ARBIB, NEW YORK."

6 November

190 5

To  
Messrs. Holmwood & Holmwood,

Dear Sirs,


SS. "AFRICA".

As we have a dispute with the builder of the above,  
we shall be obliged if you will ask the Secretary to Lloyds  
Register to give you a copy of the Lead - line Certificate of the  
above.

Yours faithfully,

*N. J. Arbib*

*1. called for  
7.11.05 -*



© 2020

Lloyd's Register  
Foundation

002410-002417-0048

to w  
ile of  
e on  
ward

tutory

tems :-

Copper, or Y.M. of  
(State if on E  
When put on, M

Boats

Masts, Yards, &c.

Condition, how asoc

(State if wedged

Sails

Equipment letter

Anchors, No. of

Cables (State if n

" length

(on bear

" Rule length

(per Tab

Hawsers & Warps

Standing & Running

al in the Register  
remain as classed

for