

WRECK
SECTION
NO. ~~623~~

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

17th May, 1960.

Classen (S)
AH/BS

Dear Sirs,

Steamer "AHERN TRADER"

In January last this ship stranded on rocks at Fredricton, Newfoundland, and she has now been declared a total constructive loss.

The case has been before the Committee who have given instructions for the notation "Wrecked 1.60" to be recorded against the vessel's name in the Register Book.


Yours faithfully,

Deputy Clerk to the
Classification Committee.

c.c. MONTREAL

The Surveyors,
ST. JOHN'S, Nfld.

002410-002417-0137



© 2020

Lloyd's Register
Foundation