

C. .80 -  
red.) 3.84 -  
- 3 1/2" -

REPORT on the

*Empire Maid*


It is submitted the Middlesbrough surveyors be informed by wire that a survey for the assignment of freeboard has been carried out in the United States, but the freeboard report has not yet been received. They should therefore not carry out a freeboard survey but verify the freeboard from a provisional certificate a Rpt 10 valid for six months.

*E.A.*

28.5.41.

NOTE. - The sound of beam should be reported on the full breadth of vessel at the gunwale.

9 1/2" -  
4 3/4" -  
4 3/4" -  
7 1/4" -  
0" -  
0" -  
0" -



© 2020

Lloyd's Register  
Foundation

002418-002426-0195

*E.A.*  
28.5.41

- 1 3/4" -  
6' 10 1/4" -