

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN

Tube Shafts, diameter as per Rule ☒ as fitted ☒ Screw Shaft, diameter as per Rule ☒ as fitted ☒ Is the { made } screw shaft fitted with a continuous
Bronze Liners, thickness in way of bushes as per Rule ☒ as fitted ☒ Thickness between bushes as per Rule ☒ as fitted ☒ Is the after end of the
propeller boss ☒ If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner

TALLINE

002427-002434-0015


GLS. 50179

It is submitted that
this vessel is eligible for
THE RECORD.

Value 2.30. Fitted for oil fuel 2 to. Above 150%
Subject to the water ballast + oil fuel lines
being isolated on arrival at Sydney or Hobart.

F.D. C.L.

P. J. 5/3/30.



Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times ☒ yes
Is the arrangement of Valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or
compartment to another ☒ yes Is the Shaft Tunnel watertight ☒ yes Is it fitted with a watertight door ☒ yes

MAIN BOILERS, &c. - (Letter for record ☒ S)

Total Heating Surface of Boilers 6345 sq ft