

6.  
Dec. 11. 49.

4 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

26 JUN 1950

VESSEL'S NAME

"BRITSUM"

REPORT

Rot.

No. 32332.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey


REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

Machinery alterations.

Port and starboard boilers fitted with N.E.M. type superheaters.  
Installation in accordance with the Rules and approved plans.

IT IS SUBMITTED that this vessel is eligible to  
remain as classed.

The Surveyor should be requested to inform this Office  
of the heating surface of the superheaters now fitted. The figure  
given in his report is indecipherable.



© 2020

Lloyd's Register  
Foundation

002435-002441-0063

X28

One 1 1/2

globe valve

22/11/49