

Framing of L

Frames in Brick
Frames from U

Req. 1.

(Received at London Office, M. 12. 44)

No. 6155 Port SUNDERLAND. Date 2. 12. 1944

We request that the Motorship Building
for British Tanker Co Ltd by Wm Doxford Sons Ltd
of about 6000 Tons. Length, BP 400' 0" breadth, MLD 56' 0" depth, MLD 30' 1"

may be Specially Surveyed while building (100 AI with freeboard) . If for a particular term
or class, state the same.

We hereby engage to pay the established Special Survey Fees as set forth in the Society's Rules, and,
in addition, any travelling and other expenses which may be incurred by the Surveyors in connexion
with the survey.

In no case can the vessel be classed until all fees, travelling expenses, &c., due thereon are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping,
which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
thereof, or the Surveyors, or other Officers or Agents of the Society."


No. 738 in Builder's Yard. Manufacturers of Engines W. Doxford Sons Ltd
Authd
N.B. 14/12/44 Ditto of Boilers WILLIAM DOXFORD & SONS, Limited.
Signature J Ramsay Keith Managing Director

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

002449-002456-0148

STRAPPED OR
LAPPED.

Side
(in Hold)



© 2020

Lloyd's Register
Foundation