

Steering Chains (Size and Test) ✓

Windlass *Steam Emerson Walker*

Boats

Ceiling in Holds, thickness and material ✓

Cargo Battens, thickness, material and s

Cargo Hatchways.—(Upper Deck) *Steel plates and angles* ✓Thickness of Hatches *60" steel* *40"*

Req. 1.

(Received at London Office, *12 DEC 1941*)

No. 5

No. *5643* Port *NEWCASTLE-UPON-TYNE* Date *8<sup>TH</sup> DECEMBER 1941*WE request that the *MOTORSHIP* Buildingfor *BRITISH TANKER COY. LTD* by *SWAN HUNTER & WIGHAM RICHARDSON L<sup>D</sup>*  
*WALLSEND SHIPYARD, WALLSEND-ON-TYNE*of *8.550* Tons. Length, *463' 0"* breadth, *M<sup>D</sup> 61' 9"* depth, *M<sup>D</sup> to U.D. 34' 0 1/2"*may be Specially Surveyed while building ( *+100A1, CARRYING PETROLEUM IN BULK* ) If for a particular term or class, state the same.

WE hereby engage to pay the established Special Survey Fees as set forth in the Society's Rules, and, in addition, any travelling and other expenses which may be incurred by the Surveyors in connexion with the survey.

In no case can the vessel be classed until all fees, travelling expenses, &amp;c., due thereon are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

No. *1673* in Builder's Yard.Manufacturers of Engines *NEPTUNE ENGINE WORKS*

Ditto of Boilers

Do.

Signature

*SWAN, HUNTER & WIGHAM RICHARDSON, LTD.*

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

002465-002470-0038

The amount of Entry Fee..... £ 11 : 0 : 0

Fees applied for,  
*31 DEC 1942*

(Special notations, where part of class,

Special Survey Fee..... £ *617* : 7 : 3

© 2020

Lloyd's Register  
Foundation