


COPY

LLOYD'S REGISTER OF SHIPPING



Port MIDDLESBROUGH

11th. November 1960.

This is to Certify that I have
"BAXTERGATE" 7072 tons gross of London
Surveyed the Machinery of the while the vessel lay afloat in this port on 1st. November 1960
and subsequently, in consequence of repairs to after main feed pump,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book. subject
to any outstanding conditions of class being dealt with as previously
recommended.

Parts now examined:
(C.S. Items only)

W. Holbar
Engineer Surveyor to Lloyd's Register
W. HOLBAR.

KEY TO ABBREVIATIONS

| | | | |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey | SGS | Steam Generator Survey |
| CS | Continuous Survey of Engines | SPS | Steampipe Survey |
| DBS | Donkey Boiler Survey | TS | Tailshaft Survey |
| ES | Engine Special Survey | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey | TSN | Tailshaft renewed |
| MES | Modified Survey of Oil Engines | TS(OG) | Tailshaft Survey—Oil Gland |
| OF | Fitted for oil fuel (date) FP above 150°F. | | |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

002477-002484-0010