

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex  
Telex No.: 24305

Telephone: ROYal 9166

Your Ref: ENGNG/FM

25th February, 1960.

Dear Sirs,

n. (H)

m.s. "BRITISH UNITY"

With reference to my letter of the 13th November last and previous correspondence, it is understood from the Society's Surveyors at Southampton that the cargo was discharged at Portland and the ship is still laid up there.

I take this opportunity to remind you that the Screwshaft Survey will become due at the end of next May and I shall be glad to learn whether you are now in a position to inform me regarding the future employment of this ship.

The Auxiliary Boiler Survey was partly held by the Southampton Surveyors on the 12th November, 1959 and to complete this survey the safety valves remain to be adjusted under steam and the oil burning system examined under working conditions, also the stoppered tubes require to be renewed by completion of this inspection. The ship will then be entitled to the notation Aux. B.S. 11.59.

Yours faithfully,

c.c. SOU.

Clerk to the  
Classification Committee.

The BP Tanker Co. Ltd.,  
Britannic House,  
Finsbury Circus,  
LONDON, E.C.3.



© 2020

Lloyd's Register  
Foundation

002490-002497-0010