

COPY

LLOYD'S REGISTER OF SHIPPING



Port SINGAPORE.

Date 28th February, 1961.

This is to Certify *that I have*

surveyed the m.v. "BRITISH MIGHT" 8245 tons gross of LONDON
on the 26th February 1961 and subsequently whilst the vessel
was afloat at Singapore on account of wear and tear repairs

and that I am transmitting to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all ^{temporary} repairs recommended by
me have been completed to my satisfaction, also that I am
recommending that she be continued as now Classed without fresh
record of Docking subject to fractured shell butt of bottom
plate "B" 6/7 (ps) and holed shell plate in "C" strake (ss)
away of Pump Room being dealt with at the next drydocking.

Surveyor to Lloyd's Register.

(L. D. PHILLIP).

KEY TO ABBREVIATIONS

AS Annual Survey
BS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."