

26 APR 1951

COPY. for London

# Lloyd's Register of Shipping.



Albany . W.A.

Port

27th March 1951

This is to Certify that I have

Steel Screw Steam

Surveyed the Boiler and Machinery of the  
Trawler " Ben Dearg " of Fleetwood 280 Gross Registered Tons,

consequent upon the vessel having been flooded to extinguish  
a bunker fire and subsequently pumped out.

and that I have transmitted to the Committee of Lloyd's Register  
of Shipping, London, a Report stating that all recommendations  
made by me in connection therewith have been carried out to  
my satisfaction, and that I have Recommended that the record of

+ L M E 7 - 49

be ~~made~~ in the Register Book in the case of this vessel.

retained  
-----

Now Done Main Engine cylinders opened up & examined & oiled  
and reassembled -- Feed pump & Bilge pump steam cylinders examined  
internally - oiled & reassembled - Boiler examined generally  
internally & externally and later seen under steam and found tight.

*Wm. P. Ferguson* ACTING FOR WM.G.DAVIES.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B1.

Attached Fremantle report No. 2585A

002498-002505-9204

© 2020

Lloyd's Register  
Foundation