


COPY

Certificate No. 0.5 0557

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

/P.



Collingwood Buildings,

Newcastle-on-Tyne, 1,

25th November, 1955

This is to Certify *that*

F. N. TANNER

the undersigned Surveyor to this Society did at the request of

Messrs. White's Marine Engineering Co. Ltd., Hobburn,

attend their works on the 30th August, 1955/ and subsequently, for the purpose of

inspecting ^{two} ~~an~~ Oil Fuel Heater designated 1745 Test No. 30564 A & B

made to the order of Messrs. Steel & Bennie Ltd., Glasgow,
and intended for S.T. "BRIGADIER".

The Heater in question ~~was~~ ^{were} subjected, in the presence of the undersigned, to hydraulic tests—the ~~strength~~ ^{Fabricated Steel Bodies} to 425 pounds per square inch, and the ~~oil space~~ ^{S.D. steel coils} to 600 pounds per square inch.

—and found satisfactory for a working oil pressure of ~~XXXXXXXXXX~~ pounds.

per square inch

The C.I. Discharge filters were also tested to 400 lbs. per sq.in. C.I. Suction filters to 200 lbs. per sq.in. 1 - C.I. Air Vessel to 400 lbs. per sq.in. and found satisfactory.

Identification Mark :-

Identification Mark :—

No. 30564 A A B

LLOYD'S TEST.

Steam Space 425 lbs. (Body)

Oil Space 600 lbs. (Coils)

Working Oil Pressure.....

16-2-55. F.V.T.

Engineer Surveyor to Lloyd's Register.

Fee: - £7. 0. 0.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society, its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of its Officers or Agents of the Society."

F.H.) 1m,8,52. (MADE AND PRINTED IN ENGLAND)

002522-002528-0195

© 2020

Foundation