

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report 18-6-1958 When handed in at Local Office 19-6-1958 Port of TORONTO
No. in Reg. Book 04956 Survey held at Port Colborne Date, First Survey 13-12-57 Last Survey 1-4-1958
(No. of Visits 3)
S.S. "C.A. ANSELL"
on the Steel
TONNAGE:— Built at Glasgow By whom Barclay, Curle & Co. Ltd. When 1929 month 5
GROSS 1940 Owners Colonial Steamships Limited
UNDER DK Managers R. Scott Misener Port belonging to Port Colborne
NET 1160

Surveyed Afloat or in Dry Dock?

Name of Dock

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 3338 Port TTO.

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE Annual SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).	
BS* Great Lakes & River	MBS*	4.54
St. Lawrence Service	MBS	3.57
Lake SS 10.54	TS (CL)	10.54
AS 4.57	SPS	2.56
DS 10.54		

ITEMS EXAMINED AND CONDITION FOUND, ETC.			
Holds including bulkheads, inner bottom plating, etc.	Good		
Bilges & ceiling.	-do-		
Tween decks.	-		
Deck & deck erections.	Good		
Machinery Space.	-do-		
Under Engines & Boilers.	-do-		
Masts, Rigging & Outfit.	-do-		
Windlass & Hawse Pipes.	-do-		
Air & Sounding Pipes with closing appliances.	-do-		
Pumps and Pumping arrangements outside machinery space.	-do-		
Steering arrangements including gear.	-do-		
W.T. Doors & Sluice valves.	-do-		
Ventilator coamings with their closing appliances.	-do-		
Hatchway coamings with their closing appliances.	-do-		
Casings, companionways and their closing appliances.	-do-		
Superstructure bulkheads with their closing appliances.	-do-		
Guard rails & freeing ports.	-do-		
Overboard discharges, also ash chutes & other shell openings.	-do-		
	EXAMINED	TESTED	CONDITION
Peaks	Yes	No	Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams (Tankers)			
Pump Rooms			
Has a Load Line Annual Renewal Survey been held?	No - Canadian Marine L.L.		
Has a Grain Survey been held?	yes		
Has a Damage Survey been held?	No		

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4.54" or "to remain as classed and to have record of docking, I, 54 and the notation Lake S.S. 4.54."

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4.58

Survey Fee U.S.S.A. \$ 66.00
Special Damage or Repair Fee (if any) \$ 4.00
Travelling Expenses \$ 12.00
Second Surveyor's Fee (if any) \$
Committee's Minute THURSDAY 7 JUL 1958
Character Assigned RS 4.58

Fees applied for,
June 24, 1958

E.G. White
Surveyor to Lloyd's Register of Shipping.

E.G. White

Note to
(m)

MBS 2.58

Noted
for
Header



© 2021

Lloyd's Register
Foundation

002529-002535-0009