

ORIG 8+9

Com for RMC

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee London Telex  
Telex No.: 24305

Telephone: ROYal 9166

LT NYMDIBLE NEW YORK (U.S.A.) (2.10.59)

Page 2.

ANTIDA REURCAB 30 YOU MAY ISSUE INTERIM CERTIFICATE AS AN UNCLASSED  
 EP PROVIDED VESSEL FROM EXAMINATION FOUND IN A SATISFACTORY CONDITION  
 VOYAGE STOP ALL MACHINERY MUST ALSO BE GENERALLY EXAMINED ACCORDANCE  
 CULAR 1959 A SATISFACTORY SEA TRIAL HELD AND ALL AUXILIARY MACHINERY  
 INCLUDING PUMPING ARRANGEMENTS TRIED WORKING STOP PROVIDED SURVEYOR  
 ISFIED ENGINE TURNED REGULARLY AND WELL MAINTAINED DURING LAY UP NO  
 ENING OUT HP CYLINDER ETCETERA NECESSARY OTHERWISE HP CYLINDER AND VALVE  
 TWO MAIN BEARINGS SHOULD BE OPENED OUT AND EXAMINED IF SURVEYOR  
 EN SATISFIED CONDITION THESE PARTS NO FURTHER OPENING OUT NECESSARY  
 OP BOILER SURVEY SHOULD BE HELD STOP ANY CARGO CARRIED TO BE OWNERS  
 SPONSIBILITY AND NO REFERENCE SHOULD BE MADE TO CARGO IN CERTIFICATES  
 SUED

cc f 50147

104

STOP CONCLUDE YOU WILL ISSUE LOADLINE CERTIFICATE AFTER

© 2021 continued..



Lloyd's Register  
Foundation

002524-002535-0082-2

ORIG 8 + 9

Comm for RMC

COPY

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee London Telex  
Telex No.: 24305

Telephone: ROYal 9166

LT NYMDIBLE NEW YORK (continued)  
Page 2.

DISFACTORY RENEWAL SURVEY

COMMITTEE

cc F/bd Dept



© 2021

Lloyd's Register  
Foundation

002529-002535-0082 2

Com to ...