

167 Recd 4.20

15 AUG 1959

5/8

E LON
7 LN

E LON
BENHAVN 44/43 5 1552 NORTHERN
E LONDON

NE 03444 OWNERS ASK IF AFTER DRYDOCKING STOP SURVEY
BYBOILER STOP TEST OF MACHINERY UNDER WORKING CONDITIONS
MAY PROCEED TO JAPAN FOR REBUILDING AT NEW OWNERS EXPENSE
SENT OWNER TO BELIVER SHIP AT JAPAN WIRE REPLY =

+
44 +
O BLOS

E LON



© 2020

Lloyd's Register
Foundation

002536-002542-0180

32
H 22

Submitted for approval
provided found satisfactory for
the desired voyage as an unclassified
ship.

5:8:59

Report:

Submitted for approval re machinery & donkey boiler but
Screwshaft should be examined before leaving tomorrow.

5/8/59

COPY TO FBI



© 2020

Lloyd's Register
Foundation