

Lloyd's Register of Shipping.

Ship's Name "BENIN PALM" Official No. 164279

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in _____

Existing small hatch openings P.S. sides, to side bunker pockets, now dispensed with and deck openings plated over.

Copy of above attached to ship's copy of C.11.

M. Mackenzie.

*Superintendent
17th September 1951.*

G.H.W.

18 OCT 1951

