

22 NOV 1917

Sent to Chief Surveyors

21. 11. 17

Received from Chief Surveyors

VESSEL'S NAME

H. S. Vessel 'Lee Lee'

Report

Don

No. 79719

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

The vessel was classed in March last subject to the inner surface of the bottom plating which was coated with tar sprinkled with cement & again coated with tar being examined within 6 months from the completion of the vessel.

The Owners now state that at present they are unable to submit the vessel for the necessary examination as she is on important Government Service on the North Coast of Scotland, and they hope the Committee will defer the examination required until a suitable opportunity.

They point out the sister vessel, S.S. Cristo, has been examined after 6 months service, and the coating of the inner surface of the bottom found satisfactory. (Correct for Repair)

It is submitted action might be deferred for the present.



© 2020

 22. 11. 17  
 Lloyd's Register  
 Foundation

002550-002558-0174