

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port CALCUTTA

12th May, 1959.

This is to Certify that I have

Tailshaft part

Surveyed the Boiler/and/Machinery of the ST. "EMPIRE OBERON" 242
tons gross of Calcutta on the 21/12/58 and subsequently whilst
the vessel lay afloat and in drydock at this port for Docking,
MBS, TS and Repairs,

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have

Recommended that the record of MBS 12/58 and TSOC 2/59


be made in the Register Book in the case of this vessel, subject to
main engine bedplate repair (aft transverse girder Metalocked)
being specially examined and dealt with as may be considered
necessary before the end of November, 1959.

E. D. Cook

E. D. COOK.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
it be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

002568-002576-0167