

orig. with Pubs

16th August,

61.

BRISTOL

m.s. "B.P. EXPLORER"

303

03115

With reference to my memorandum of 15th and your reply of 16th March, it has since been learned that this ship was refloated and towed into Sharpness Dock. However, as nothing further has been reported, I shall be glad if you will let me know whether repairs have been commenced.

17th August, 1961.

Repairs commenced and progressing slowly.

NOTES.
BRS 6.61.

Compl.



© 2020

Lloyd's Register
Foundation

002592-002601-0265