

Received from Chief Ship Surveyor

26 SEP 1960

SHIP'S NAME "DARONIA" REPORT Mel. No. 17812

EA

Outstanding Conditions of Class:

SUBJECT to shell plates G.5-13 (p.s.a) and G.5-14 (s.s.a) (wastage) being specially examined and dealt with as necessary next Special Survey.

S.R.L. Appendix. (As before or None) ~~XXXXXXXXXX~~

Nature of Present Survey: (Afloat and in dry dock) ~~XXXXXXXXXX~~

Temporary repairs to shell plates D.5 frames 96-97 (p.s) on account of leakage.

Recommendation: SUBJECT as above and to shell plate D.5 frames 96-97 (p.s) being specially examined and dealt with as necessary by 11,60.

As Now Subject.

IN S.R.L. APPENDIX.
Indents in keel plate No.16.



©

23/9/60
2020

Lloyd's Register
Foundation