





The Surveyor reports some repairs effected to the Main Boilers.

It is submitted that this vessel is eligible to remain as **CLASSED**.

JW  
65/10/18

LEAVE THIS SPACE BLANK

Survey fees ...  
Damage fee ...  
Expenses... ..  
Date when A/c rendered.....

- 32 Essential Independent Pumps (Identify by position) .....
- 33 Bllge, Ballast & Oil Fuel Suction Lines, Fittings & Controls .....
- 34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary? .....
- 35 Fresh Water Coolers ..... 36 Lub. Oil Coolers ..... 37 Heaters (state service) .....
- 38 Independent Air Compressors, Coolers & Safety Devices .....
- 39 Air Receivers & Safety devices—Main .....
- 40 Auxiliary .....
- 41 Oil Fuel Tanks (Not forming part of hull structure) .....
- 42 Evaporators ..... 43 Have Evaporator Safety Valves been tested under steam? .....
- 44 Steering Machinery ..... 45 Windlass ..... 46 Fire Extinguishing Arrangements .....

AUXILIARY ENGINES (Identify by position).....

PROPULSION		ELECTRICAL EQUIPMENT	
PORT	STARBOARD		AUXILIARY EQUIPMENT
a Generators .....		i Generators & Governors .....	
b Exciters .....		m Motors .....	
c Air Coolers .....		n Switchboards & Fittings .....	
d Motors .....		o Circuit Breakers .....	
e Air Coolers .....		p Cables .....	
f Control Gear, Cables, etc. ....		q Insulation Resistance .....	
g Insulation Resistance .....		r Steering Gear Generators and Motors .....	
h Insulating Oil Test .....		s Navigation Light Indicators .....	
i Overspeed Governors .....			
j Magnetic Couplings .....			
k Air Gap .....			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN ..... AUXILIARY, DONKEY or PRESS .....

- Superheaters .....
- Safety Valves .....
- Mountings, Doors & Fastenings .....
- Safety Valves Adjusted to { Sat. ....  
Spt. ....
- Boiler Securing Arrangements .....
- Main Economisers .....
- Steam Heated Steam Generators ..... Exhaust Gas Heated Economisers .....
- Were Oil Burning System & Remote Controls examined working in accordance with Rules? ..... Forced Circulating Pumps .....
- Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules? ..... Funnel .....

EXAMINATION & TESTING OF STEAM PIPES (State material)

- Main ..... Auxiliary (over 3 in. bore) .....
- Were Copper Pipes annealed? ..... Have Saturated Pipes in cylindrical boiler smoke boxes been tested? .....

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)