

F.E.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S.S. "Florence Cooke"* Rpt. *Nw.* No. *76968*

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 2A/5/92.)

Longl.
 Transverse No. *1324.58* Depth "d" *9.16'*
between
 Framing Tables Nos *2+3* Description *Bull angle as approved.*
 Longitudinal No. *4246.58*
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{12.78 \text{ to upper dk.}}{9.87 \text{ " R.P. dk.}}$
 Deck Sheerstrake *as approved.*

This vessel has been built in accordance with the Revised Rules, and the Builders obtained the Owners' sanction thereto.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to

be classed *100.A.1. (Steel)*

1 Dk (Stl) "well dk."

FPT 36t, APT 19t.

FK, 3BH, Cem, Lloyd A+CP, 9 44', B 13', F 19'

Mchy. aft.

[Signatures]
A.W.J.
 © 2020
21/8/23.

The Surveyors should be requested to forward plans of the vessel as built for record in this office.

002630-002638-0218

