

28.11.38.

4 E

ived by Chief Engineer Surveyor

Received from Chief Engineer Surveyor.....

EL'S NAME "DASHWOOD" Rpt. Sld. No. 34671

emarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH

This case is fully stated in an endorsement dated 21. 6. 47.

The Sunderland Surveyors have now forwarded a First Entry report on the electrical equipment together with amended plans and these have been found satisfactory.

IT IS SUBMITTED the class of this vessel's machinery is eligible to remain as previously stated, viz:- "Examined 4.47", (Class Contemplated).



© 2021 Lloyd's Register Foundation
1. 10. 47.

Ent *J.F.*

002647-00652-0014

INCH
4
3
3/2
6
5/8
20/8
20/8
5
170
0