

POSTPONED SURVEYS

of the S.S. "DALEGARTH FORCE" No. _____ in R.B.

3 - 1918. Tonnage _____ Owners _____

Port of Registry _____

Last docking date 1.57.

is due Main Boiler Survey due 1.58.

The class is subject to side shell plating in way of kehold (s.s.) (leakage) being permanently repaired by next docking.

sed to be _____

ks. The Secretary at Liverpool state that the ship is laid up with no likelihood of trading in the near future.

Surveyors' recommendations Submitted action to be deferred. Sub

14/8/58

Committee's Minute _____

THURSDAY 19 AUG 1958

Deferred,

subject

© 2020

Lloyd's Register
Foundation

002653-002658-0036