

"NIKOBAR" ex. "RUSHVILLE VICTORY"

This case is fully stated in an endorsement dated 28. 8. 47.

A number of queries were raised with the Baltimore Surveyors and satisfactory replies have been received with the exception that the electric cables from the emergency generator set are stated to be in varnished cambric having two cables per pole each of 7/.024" diameter. This is insufficient for the current produced by this generator. The Copenhagen Surveyors should therefore be advised and be asked to confirm whether in fact there are four cables of this size per pole. If this be the case the matter is in order.

Insert in Reg. Book:-

H.S. 11352 m.ft.

M.N. 1520.

Smt.

Write Opn:
& for Mr. Chinnock
to insert 115 & m.n.



© 2020

3.12.47.

Lloyd's Register
Foundation

002653-002658-0215