

February 3, 1939.

S.S. "ROCKCLIFFE HALL"

Freeboard assigned is minimum international
freeboard, plus penalty for low hatch coamings. ✓

It is noted that hatch beams have been reinforced,
and that provision has been made for the fitting
of lifelines. ✓

If steel doors (at present $1\frac{1}{2}$ " wood) are being
fitted to forecastle bulkhead, please insert the
necessary particulars at back of load line certificates
and inform this office accordingly. ✓



© 2020

Lloyd's Register
Foundation