

COPY.

Lloyd's Register of Shipping.



ANNUAL SURVEY

Motor Vessel "FORT HEARNE" of Montreal. 382 tons gross Register

Port Tuktuyaktuk. N.W.T.

July, 12th 1951.



This is to Certify that

the undersigned Surveyor to this Society did at the request of the Owners, attend the wood motor vessel "FORT HEARNE" of Montreal, 382 tons gross Register, as she lay afloat at Tuktuyaktuk, N.W.T. 12th day of July.....1951, and subsequent dates, in order to survey the vessel in accordance with the Rules of the Society for annual survey.

Examined stem and stern posts, sheathing, bow protection plates and hull planking, as far as seen afloat.

Examined decks, bulwarks, hatches and hatch coamings, covers and tarpaulins and wedges and battens fore and afters, beam knees, ceiling timbers and bulkheads.

Examined masts and rigging.

Examined ventilators, freeing ports, doors, coamings and all openings to Crew's quarters, engine room, saloon and galley.

Examined and tested steering gear.

Examined windlass, hawse pipes and anchors.

Examined pumps and piping.

Verified load line marks. (As shown on load line certificate)

MACHINERY:-

Main engine cylinders opened and examined.

Pistons, crosshead, pins and bearings, crank and main bearings examined.

Air tanks examined externally and working pressure pumped up and safety valves examined.

Main engines closed and tried out under working conditions.

Auxiliary machinery opened, examined, closed and tried out under working conditions.

Examined fuel tanks externally.

Examined all valves, pipes and connections.

Examined electric installations.

In view of this annual condition survey, I am of the opinion that this vessel is in good condition and eligible to remain as now classed in the Register with fresh record of survey.

SIGNED.....

S. L. B. Mudge, R. L. H. J.

Surveyor.

Master.

Chief Eng.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."