

15 SEP 1960

SHIP NAME "FRASCA" REPORT CCO No. 5997

Standing Conditions of Class: SUBJECT to the (holed) shell plating in way of A.P. tank being specially examined and dealt with as necessary next dry docking.

L. Appendix. (~~As before~~ None)

Condition of Present Survey: (Afloat and in dry dock)

Docking: Wear and tear repairs including further repairs to shell plating in way aft peak.

Recommendation: SUBMITTED record of DS 6,60 be assigned, subject to shell plating forward and aft in way aft peak tank, all starboard side (corroded and **doubled**) being specially examined and dealt with as necessary next drydocking.

DS 6,60 Subject  
Amended



©

Lloyd's Register  
Foundation