

COPY

002711-002716-0078

Received from Chief Ship Surveyor

23 MAR 1957

"INDUS MARU"

REPORT

Smk.

No.

689

Conditions of Class: Subject to shell plate D.2 (p.s.) in
way of No.5 hold being renewed on ship's arrival at Kasado
from present voyage, and to 60 fathoms of worn chain cable
on board being renewed by completion of the Special Survey.

ACTION and NOTATION of 'SS Kob. 6,56' DEFERRED
for completion of the Special Survey by 5,57.
of Class (B) (As before ~~xxxNone~~)

SPECIAL SURVEY (C) due 5,56 - largely held Kob. 6,56.

Present Survey: (~~xxxxxx~~ in dry dock)

Repairs to shell plate D.2 (p.s.) as above and adjoining
shell plating (thin).

ures:

Certificate in order (~~Yes-None~~)

*except omit D.S. in view of
dtg due 5/54.*

Adding: (If any for S.S.) ~~xxxxxx~~

TO COMPLETE THE S.S.:- 2nd deck plating TO BE EXAMINED.
60 fathoms of worn c.c. TO BE RENEWED.

Completed by: See below.

on:

SUBMITTED ACTION and NOTATION of 'SS Kob. 6,56'
continue to be DEFERRED until 5,57 for
completion of the Special Survey (2nd deck
plating to be examined and 60 fathoms of worn
chain cable to be renewed), without special
conditions but with Endorsement of Certificate.

*Worn
Renewed
S.S. 3729
(Kob. 6,56)*

As Now. Without.

S.S. PART HELD.

ENDORSEMENT OF CERTIFICATE

Indented bottom plating etc. (forward & aft) (p.s.)

Owners' proposal to complete the Special Survey
in 6,57 (i.e. one month beyond expiry of the
year of grace) instead of 5,57 as previously
recommended, is submitted for (favourable)
consideration. *Refer Memo to (17/4/57)*
and from (17/5/54) Kobe Surveyors.

23.5.57.

Particulars of Classification (which must be entered in Register Book & Supplement)
Engi
Boil
Tails
Steam
f assigned)
d now verifi
n?
starboa
lock in c
Now Don
frame No
02, E3 (I
plating
er Items:-
or Y.M.
State if on Fe
fitted, Month
Yards, &c.
on, how aso
(State if wed
ent letter
s, No. of
(State if no
length
(on board
tule length.
locker
s & Warps
g and Runn
in the Reg
remain as cl
resh r
platin