

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

30th December, 1960.

(S)

Dear Sirs,

Steamer "INGEROIS"

The case of the above named vessel has received the consideration of the Committee today in the light of the comments contained in my letter to you of the 11th November.

The Committee have been informed that up to the present no replies have been received to the cablegrams sent to you on the 9th and 21st instant. In the circumstances the Committee do not feel justified in maintaining this vessel's class and have, therefore, given instructions for a notation of "Repairs required - Class suspended 12.60" to be recorded against the ship's name in the Supplement to the Register Book.

They desire the Owners to be informed of this decision and of the fact that if no satisfactory proposal for the outstanding matters to receive attention at an early date is received by Friday next 6th January, they will then expunge the class altogether.

Yours faithfully,

Clerk to the
Classification Committee.

The Surveyors,
HELSINGFORS.



© 2020

Lloyd's Register
Foundation

002711-002716-0168