

January 27, 1939.

S.S. "GEORGE L. BATON"

Freeboard assigned is minimum international
freeboard plus penalty for low coamings. ✓

It is noted that lifelines have been fitted
also that the hatch beams have been reinforced
to Rule standard. ✓



© 2020

Lloyd's Register
Foundation

002717-002724-0033