

# Lloyd's Register of Shipping.

/P.



Collingwood Buildings,

12th October,

49

Newcastle-on-Tyne, 1,

19

### This is to Certify that

A. HUNTINGFORD

the undersigned Surveyor to this Society did at the request of

The Wallsend Slipway & Engineering Co. Limited

and subsequently,

attend their works on the 16th September, 1949 for the purpose of

inspecting ~~two~~ two Fabricated Steel <sup>No. 575</sup>  
~~Oil Fuel Heater~~ <sup>No. 576</sup> designated X1519 Test No. s.19419, 19420

made to the order of Messrs. Swan Hunter & Wigham Richardson Ltd.,  
s.s. "HARPERLEY",

and intended for F.1528.

~~was~~ <sup>were</sup>

The Heater<sup>s</sup> in question ~~was~~ <sup>were</sup> subjected, in the presence of the

undersigned, to hydraulic tests—the steam space to 450 pounds

per square inch, and the oil space to 400 pounds per square inch

—and found satisfactory ~~for a working oil pressure of~~ <sup>two cast iron auto-klean oil fuel discharge</sup> Strainers, W.T. 400 lbs. ~~per square inch.~~

Identification Mark:—

No. 19419 19420

LLOYD'S TEST.


Steam Space 450 lbs.  
400 lbs.

Oil Space 400 lbs.

Working Oil Pressure 15-9-49 20-9-49.

A.H. A.H.  
Fee:—£4. 0. 0.

Engineer Surveyor to Lloyd's Register.



© 2020

Lloyd's Register  
Foundation

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."